

कार्यपालक अभियंता का कार्यालय
भ.नि.वि., पटना पश्चिम भवन प्रमंडल, दानापुर, पटना-23
(शास्त्रीनगर, समुदायिक भवन, पटना-23)

पत्रांक—359330

दिनांक—29/1/18

प्रेषक,

कार्यपालक अभियंता
पटना पश्चिम भवन प्रमंडल
दानापुर, पटना।

सेवा में,

निदेशक,
माउन्ट लिटेरा जी स्कूल,
मौजा—बाकरपुर,
थाना—सगुना मोड़, खगोल रोड
दानापुर, पटना-801503

विषय:— माउन्ट लिटेरा जी स्कूल, मौजा—बाकरपुर, थाना—सगुना मोड़, खगोल रोड, दानापुर,
के भवन ठोसता प्रमाण पत्र के संबंध में।

प्रसंग:— आपका पत्रांक ML25/DAN/2018/0354 एवं सहायक अभियंता, भ0अ0प्र0, दानापुर का
पत्रांक 13 अनु0 दिनांक 27.1.18.

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र के संबंध में कहना है कि सहायक अभियंता, भवन अवर
प्रमंडल, दानापुर का प्रतिवेदन द्वारा विषयांकित स्कूल का निरीक्षण किया गया निरीक्षणोपरान्त पाया गया
भवन ठोरा एवं गजबूत है।

अतः उक्त स्कूल को निरीक्षण प्रतिवेदन का छाया प्रति संलग्न करते हुए ठोसता प्रमाण पत्र निर्गत
किया जाता है।

अनु0—यथोक्त।

विश्वासभाजन

कार्यपालक अभियंता

पटना पश्चिम भवन प्रमंडल,
दानापुर, पटना।

OFFICE OF ASSISTANT ENGINEER

Danapur sub-division, Patna west building division Danapur, Patna.

Letter No. 13 (370) /

Date 27/01/18 /

From,

Assistant Engineer
Danapur Sub-division,
Patna west Building Division,
Danapur, Patna

To,

Executive Engineer
Patna west Building Division, Danapur Patna

Sub- Building safety certificate for the school Building " MOUNT LITERA ZEE
SCHOOL" at khagaul Road Danapur, Patna.


Ref:- Your Letter no.-221 on Dated-16.01.2018

Sir,

With Reference to above subject, after Physically Verification and observation of Structural Plans building is structurally safe. (C/S Photo copy of BUILDING SAFETY CERTIFICATE which is given by Shailendra Kumar, Structural Engineer, Attached.)

Forwarded for information and necessary action.

Your's faithfully



Assistant Engineer
Danapur Sub-division,
Patna west Building Division,
Danapur,

Memo no....13 (370)

date....27/01/18

Copy forwarded to:- Director, Mount litera zee school, Khagaul Road, Danapur, Patna for information.



Assistant Engineer
Danapur Sub-division,
Patna west Building Division,
Danapur,

Shailendra Kumar
Structural Engineer.

E.No. STRE/18/15
Nagar Parishad Danapur Nizamat
Govt. Of Bihar
Danapur, Patna.

File No.: 144/17

Date: 14.07.2017.

BUILDING SAFETY CERTIFICATE.

Building Safety Certificate for the School building of **MOUNT LITERA ZEE SCHOOL**, in Mauza- Babakarpur, Tauzi No. 5059, S. Plot No. 111, 113, Khata No. 31, 52, Thana No. 35, at Saguna more, Khagaul Road, Danapur, Patna.

We certify that the structural plans of the building met structural safety requirement for all situations including natural disasters, as applicable, as situated under part 6 Structural Design of the National Building Code of India, IS 456:2000, IS 1893:2002, IS 13920:1993, SP:16 and other relevant codes. The design has been done after detailed soil test and we are satisfied as to the adequacy of soil test carried out.

The Building also designed with Earth Quake Resistance Zone -IV as per IS Code 1893:2002. The Building is structurally safe and sound.

The Building is Structurally Safe

C/S

27/01/18
Assistant Engineer
Building Sub division
DANAPUR

Shailendra Kumar

(Shailendra Kumar)
Structural Engineer.

SHAIENDRA KUMAR
Structural Engineer
Empanelment No STRE/18/15
Nagar Parishad, Danapur, Nizamat